

MAIL 22/11/17

LOCHINVAR Wastewater

Rutherford NSW 2320
 Telephone: 02 4932 1011
 accounts@gardenmaster.com.au

87600

QUARTERLY MAINTENANCE REPORT

OWNER Downer EOI Mining - OBS BRAND: Enviro Cycle NEXT DUE: Jan
 ADDRESS 8 Melva Place MH Thorley CUST N°: 1615
 DATE 6/11/17 COUNCIL Singtelon COUNCIL N°: _____

ENTERED
891750

		COMMENTS
IS THE SITE SAFE?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
IS THERE A CONFINED SPACE?	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no	
IS THERE ANY ELECTRICAL HARD WIRING?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
ELECTRICAL		
GENERAL CONDITION	<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> FAIR <input type="checkbox"/> POOR	
ALARMS TESTED AT TANK	WATER - <input checked="" type="checkbox"/> yes <input type="checkbox"/> no AIR - <input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
ELECTRICAL COMPARTMENT CLEANED	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
AIR BLOWER	<input type="checkbox"/> 60 <input checked="" type="checkbox"/> 80 <input type="checkbox"/> 100 SERIAL No.	
AIR & SLUDGE RETURN SYSTEMS		
ODOUR	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no AIR FILTER - <input checked="" type="checkbox"/> replaced <input type="checkbox"/> cleaned	
SLUDGE RETURNED TO PRIMARY CLEAR	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
SEPTIC CHAMBER		
PUMP OUT NEEDED	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no	
INLET AND JUNCTION CLEAR	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
IRRIGATION CHAMBER		
FREE CHLORINE	mg/litre TABLETS REPLACED <input checked="" type="checkbox"/>	
WATER PUMP OPERATION PRESSURE	<input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor	
IRRIGATION LINE		
CONDITION	<input checked="" type="checkbox"/> ok <input type="checkbox"/> inaccessible <input type="checkbox"/> replace/repair	
SPRAYS	<input checked="" type="checkbox"/> ok <input type="checkbox"/> cleaned <input type="checkbox"/> replace/repair	
SUB SURFACE FILTER	<u>N/A</u> <input checked="" type="checkbox"/> ok <input type="checkbox"/> replaced	
DISPOSAL AREA	<input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor PONDING - <input type="checkbox"/>	
SUBSURFACE IRRIGATION	<u>N/A</u> <input checked="" type="checkbox"/> yes <input type="checkbox"/> no FLUSHED - <input type="checkbox"/> yes <input type="checkbox"/> no	

COMMENTS
Tank/System is clean & working well. Installed valve for water sampling. Walked Ensometal office through the working of the system.

TECHNICIAN (PRINT) Warren SIGNED [Signature]
 PAYMENT TERMS STRICTLY 7 DAYS

Tax Invoice/Payment Slip			
Name:		Invoice # 87600	
Qty	Description	Amount	Total
1	Quarterly fees are now due. Thanks.		\$140
1	Labour charges.		\$85
1	Air Blower Filter		\$10
Biller Code: 256701		GST	\$9.50
Please call office for Credit Card payments		Total	\$244.50
Westpac Banking Corporation		Payment Now Due	
BSB: 032 596		Note: Our banking details have changed	
Account: 214 902			
Ref: 16155			

QUARTERLY MAINTENANCE REPORT

OWNER Downer EDI Mining-Blasting Services BRAND: Enviro Cycle NEXT DUE: Oct
 ADDRESS 8 Melva Place Mt Tharley CUST N°: 1615
 DATE 4/8/17 COUNCIL Singleton COUNCIL N°: _____

		COMMENTS	
IS THE SITE SAFE?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	ENTERED 666432	
IS THERE A CONFINED SPACE?	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no		
IS THERE ANY ELECTRICAL HARD WIRING?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		
ELECTRICAL			
GENERAL CONDITION	<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> FAIR <input type="checkbox"/> POOR		
ALARMS TESTED AT TANK	WATER - <input checked="" type="checkbox"/> yes <input type="checkbox"/> no AIR - <input checked="" type="checkbox"/> yes <input type="checkbox"/> no		
ELECTRICAL COMPARTMENT CLEANED	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		
AIR BLOWER	60 <input checked="" type="checkbox"/> 80 <input type="checkbox"/> 100 SERIAL No.		
AIR & SLUDGE RETURN SYSTEMS			
ODOUR	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no AIR FILTER - <input checked="" type="checkbox"/> replaced <input type="checkbox"/> cleaned		
SLUDGE RETURNED TO PRIMARY CLEAR	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		
SEPTIC CHAMBER			
PUMP OUT NEEDED	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no		
INLET AND JUNCTION CLEAR	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no		
IRRIGATION CHAMBER			
FREE CHLORINE	mg/litre <input checked="" type="checkbox"/> TABLETS REPLACED <input checked="" type="checkbox"/>		
WATER PUMP OPERATION PRESSURE	<input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor		
IRRIGATION LINE			
CONDITION	<input checked="" type="checkbox"/> ok <input type="checkbox"/> inaccessible <input type="checkbox"/> replace/repair		
SPRAYS	<input checked="" type="checkbox"/> ok <input type="checkbox"/> cleaned <input type="checkbox"/> replace/repair		
SUB SURFACE FILTER	<u>N/A</u> <input checked="" type="checkbox"/> ok <input type="checkbox"/> replaced		
DISPOSAL AREA	<input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor PONDING - <input type="checkbox"/>		
SUBSURFACE IRRIGATION	<u>N/A</u> <input checked="" type="checkbox"/> yes <input type="checkbox"/> no FLUSHED - <input type="checkbox"/> yes <input type="checkbox"/> no		
COMMENTS			
<u>Tank/System is clean & working well</u>			

RECEIVED
4 AUG 2017
BY: Jenna Durr

TECHNICIAN (PRINT) Warren SIGNED [Signature]
 PAYMENT TERMS STRICTLY 7 DAYS

Tax Invoice/Payment Slip			
Name:		Invoice # 90707	
Qty	Description	Amount	Total
1	Air Blower filter		\$ 10-
1	Quarterly fees are now due. Thanks		\$140-
<u>P/O # 3214637 20215038.</u>			
B PAY THE WAY TO PAY	Biller Code: 256701	Please call office for Credit Card payments	GST \$ 1
	Ref: 16155	Westpac Banking Corporation	Total \$151-
		BSB: 032 596 Account: 214 902	Payment Now Due
		Note: Our banking details have changed	


QUARTERLY MAINTENANCE REPORT

OWNER Downer EDI Mining-Blasting Services BRAND: Enviro Cycle NEXT DUE: July
 ADDRESS 8 Melva Place Mt Thorley CUST N°: 1615
 DATE 19/5/17 COUNCIL Singleton COUNCIL N°: _____

		COMMENTS
IS THE SITE SAFE?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	ENTERED 1734708
IS THERE A CONFINED SPACE?	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no	
IS THERE ANY ELECTRICAL HARD WIRING?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
ELECTRICAL		
GENERAL CONDITION	<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> FAIR <input type="checkbox"/> POOR	
ALARMS TESTED AT TANK	WATER - <input checked="" type="checkbox"/> yes <input type="checkbox"/> no AIR - <input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
ELECTRICAL COMPARTMENT CLEANED	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
AIR BLOWER	<input type="checkbox"/> 60 <input checked="" type="checkbox"/> 80 <input type="checkbox"/> 100 SERIAL No.	
AIR & SLUDGE RETURN SYSTEMS		
ODOUR	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no AIR FILTER - <input checked="" type="checkbox"/> replaced <input type="checkbox"/> cleaned	
SLUDGE RETURNED TO PRIMARY CLEAR	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
SEPTIC CHAMBER		
PUMP OUT NEEDED	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no	
INLET AND JUNCTION CLEAR	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
IRRIGATION CHAMBER		
FREE CHLORINE	mg/litre TABLETS REPLACED <input checked="" type="checkbox"/>	
WATER PUMP OPERATION PRESSURE	<input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor	
IRRIGATION LINE		
CONDITION	<input checked="" type="checkbox"/> ok <input type="checkbox"/> inaccessible <input type="checkbox"/> replace/repair	RECEIVED 19 MAY 2017
SPRAYS	<input checked="" type="checkbox"/> ok <input type="checkbox"/> cleaned <input type="checkbox"/> replace/repair	
SUB SURFACE FILTER	<u>N/A</u> <input checked="" type="checkbox"/> ok <input type="checkbox"/> replaced	
DISPOSAL AREA	<input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor PONDING - <input type="checkbox"/>	
SUBSURFACE IRRIGATION	<u>N/A</u> <input type="checkbox"/> yes <input type="checkbox"/> no FLUSHED - <input type="checkbox"/> yes <input type="checkbox"/> no BY: _____	
COMMENTS <u>System had a blockage between tanks. Fed hose up & partially unblocked. May need a plumber</u>		

TECHNICIAN (PRINT) Warren SIGNED WJ
 PAYMENT TERMS STRICTLY 7 DAYS

Tax Invoice/Payment Slip

Name:		Invoice # 89164	
Qty	Description	Amount	Total
1	Air Blower Filter		\$10-
1	Quarterly fees are now due. Thanks P/O #3214637 2017/1512.		\$140-
 Ref: <u>16155</u>	Please call office for Credit Card payments Westpac Banking Corporation BSB: 032 596 Account: 214 902		GST \$ 1 Total \$151- Payment Now Due
	Note: Our banking details have changed		
	THE WAY TO PAY		



Lochinvar Wastewater

321 New England Highway
Rutherford NSW 2320
Telephone: 02 4932 1011
accounts@gardenmaster.com.au



Tax Invoice No.

86464

QUARTERLY MAINTENANCE REPORT

OWNER Downer EDI Mining-Blasting Services BRAND: EnviroCycle NEXT DUE: April
 ADDRESS 8 Melva Place Mt Thorley CUST N°: 1615
 DATE 1/2/17 COUNCIL Singleton COUNCIL N°: _____

		COMMENTS
IS THE SITE SAFE?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
IS THERE A CONFINED SPACE?	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no	
IS THERE ANY ELECTRICAL HARD WIRING?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
ELECTRICAL		
GENERAL CONDITION	<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> FAIR <input type="checkbox"/> POOR	
ALARMS TESTED AT TANK	WATER - <input checked="" type="checkbox"/> yes <input type="checkbox"/> no AIR - <input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
ELECTRICAL COMPARTMENT CLEANED	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
AIR BLOWER	<input type="checkbox"/> 60 <input checked="" type="checkbox"/> 80 <input type="checkbox"/> 100 SERIAL No.	
AIR & SLUDGE RETURN SYSTEMS		
ODOUR	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no AIR FILTER - <input checked="" type="checkbox"/> replaced <input type="checkbox"/> cleaned	
SLUDGE RETURNED TO PRIMARY CLEAR	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
SEPTIC CHAMBER		
PUMP OUT NEEDED	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no	
INLET AND JUNCTION CLEAR	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
IRRIGATION CHAMBER		
FREE CHLORINE	mg/litre TABLETS REPLACED <input checked="" type="checkbox"/>	
WATER PUMP OPERATION PRESSURE	<input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor	
IRRIGATION LINE		
CONDITION	<input checked="" type="checkbox"/> ok <input type="checkbox"/> inaccessible <input type="checkbox"/> replace/repair	
SPRAYS	<input checked="" type="checkbox"/> ok <input type="checkbox"/> cleaned <input type="checkbox"/> replace/repair	
SUB SURFACE FILTER	<u>N/A</u> <input checked="" type="checkbox"/> ok <input type="checkbox"/> replaced	
DISPOSAL AREA	<input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor PONDING - <input type="checkbox"/>	
SUBSURFACE IRRIGATION	<u>N/A</u> <input type="checkbox"/> yes <input type="checkbox"/> no FLUSHED - <input type="checkbox"/> yes <input type="checkbox"/> no	
COMMENTS <u>Tank/System is clean & working well.</u>		



TECHNICIAN (PRINT) Warren

SIGNED WJ

BY: Terna Orr

PAYMENT TERMS STRICTLY 7 DAYS

Tax Invoice/Payment Slip

Name:		Invoice # 86464	
Qty	Description	Amount	Total
1	<u>Quarterly fees are now due. Thanks.</u> <u>p/o # 3214637</u>		<u>\$140</u>
 Ref: <u>16155</u>		Please call office for Credit Card payments Westpac Banking Corporation BSB: 032 596 Account: 214 902 Note: Our banking details have changed	
		GST	
		Total	<u>\$140</u>
		Payment Now Due	